Work Order Bid (ID)



WORK ORDER INFORMATION

Work Order Name: WO/17017UC-0497/1

Work Order Type: Weatherization Audit Name: 17017UC-0497

CLIENT INFORMATION

Client ID: 17017UC-0497

AGENCY INFORMATION

Agency: Upper Cumberland H R A **Agency Phone:** (931) 528-1127

Address: 3313 Williams Enterprise Drive Fax: Cookeville, TN 38506 **Email Address:**

Agency Contact: Patterson, Danny Work Phone:

Cell Phone: (931) 261-1664

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

1955 site built

Measures

Measure 1 In	filtration Redctn			Componen	ts			Inspected
Seal : Caulk	access block hole and insu around tub c interior and exterior windo e 10 windows	•		ndow with Lo	ow E			
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Miscellaneous Supplies	Infiltration Reduction	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 2 D'	WH Pipe Insulation			Componen				Inspected
Comment	·			Estimated	1		Actual	
Comment # Material / Labor	Description / Comment	Units	Qty	•		Qty	Actual Unit Cost	Inspected Total
Comment	·	Units Each		Estimated	1	Qty		
Comment # Material / Labor	Description / Comment DHW Pipe Insulation		Qty	Estimated	1	Qty		
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation wrap water pipes	Each	Qty 1	Estimated	1	Qty		
Comment# Material / Labor1 Insulation	Description / Comment DHW Pipe Insulation wrap water pipes	Each	Qty 1	Estimated	1	Qty		
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation wrap water pipes	Each	Qty 1	Estimated	1	Qty		
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation wrap water pipes	Each	Qty 1 1	Estimated	1			

Measure 3 Atti	c Ins. R-30			Componen	ts ATC			Inspecte
Comment								
		Estimated			Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Blown Cellulose - R-30	SqFt	1324					
Other Detail								
			Measure	e Sub Total:		,	Sub Total:	
Measure 4 Sto	rm Windows			Componen	<i>t</i> s B2,G1	5,C5,H	I16,C9	Inspecte
	rm Windows			•		5,C5,H		Inspecte
	rm Windows			Componen Estimated		5,C5,H	I16,C9 Actual	Inspecte
Comment	rm Windows Description / Comment	Units	Qty	•		5,C5,⊢ 		Inspecte Total
Comment # Material / Labor		<i>Units</i> Each Window		Estimated			Actual	
Comment # Material / Labor	Description / Comment	Each	Qty	Estimated			Actual	
Comment # Material / Labor	Description / Comment Storm Window	Each	Qty	Estimated			Actual	
Comment # Material / Labor 3 Other	Description / Comment Storm Window	Each	Qty	Estimated			Actual	
Comment # Material / Labor 3 Other	Description / Comment Storm Window	Each	Qty	Estimated			Actual	
# Material / Labor 3 Other	Description / Comment Storm Window	Each Window	Qty 8	Estimated		Qty	Actual	

Measure 5 DW Comment	H Tank Insulation			Componen	ts			Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Hot Water Equipment	DHW Tank Insulation	Each	1					
	R-10 minimum-use bubble wrap							
2 Labor	DHW Tank Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 6 CO Comment	Monitor is Needed			Componen	ts			Inspected
Comment				Estimated			Actual	
Comment # Material / Labor	Description / Comment	Units	Qty	-	ts Total	Qty		Inspected Total
Comment # Material / Labor	Description / Comment	<i>Units</i> Each		Estimated		Qty	Actual	
Comment# Material / Labor1 Health and Safety Items	Description / Comment		Qty	Estimated		Qty	Actual	
Comment# Material / Labor1 Health and Safety Items	Description / Comment 9-volt CO Monitor	Each	Qty 1	Estimated		Qty	Actual	Inspected Total
 Comment # Material / Labor 1 Health and Safety Items 2 Labor 	Description / Comment 9-volt CO Monitor	Each	Qty 1	Estimated		Qty	Actual	
 Comment # Material / Labor 1 Health and Safety Items 2 Labor 	Description / Comment 9-volt CO Monitor	Each	Qty 1	Estimated		Qty	Actual	
 Comment # Material / Labor 1 Health and Safety Items 2 Labor 	Description / Comment 9-volt CO Monitor	Hour	Qty 1 1	Estimated			Actual	
Comment# Material / Labor1 Health and Safety Items2 Labor	Description / Comment 9-volt CO Monitor	Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
# Material / Labor 1 Health and Safety Items 2 Labor Other Detail	Description / Comment 9-volt CO Monitor	Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

Measure 7 Smo	ke Detector is Needed			Componen	its			Inspected
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	9-volt Smoke Detector	Each	1					
2 Labor	Labor	Hour	1					
Other Detail						1		
			Measur	e Sub Total:] ;	Sub Total:	
	ed space heater d spaced heater currentl	y in home	needs	Componen to be replace		a vented		Inspected
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Unspecified	Misc Material	Each	1					
Other Detail						1		
] []		
]	Cub Total	
			Measur	e Sub Total:		,	Sub Total:	
Field Notes:								
		Work Or	der Gra	nd Total:		Gran	d Total:	